



XGEN COATING SYSTEM™

Solutions. Delivered.



APPLICATION CASE STUDY:

Project Description: Apply Product to Shower Walls & Floors in Gym Locker Room

Customer: LAC (Louisville Athletic Club)

Location: Louisville, Kentucky

Date: September, 2016

PROJECT DETAILS

Project Overview: The floors and shower walls were dingy and showed water spots. The grout was stained on the floors and in the shower stalls. The Customer wanted to restore the floors and showers to like-new condition for their members. The customer desired a gloss coating to improve appearance.

xGen Product Purchased Through: PPG Louisville

Customer: Louisville Athletic Club

PRODUCT DETAILS



xGen Product Utilized: X-PROTECT Performance Topcoat - High Gloss


Features & Benefits: The tile floors and shower walls were stripped and coated with X-PROTECT. The grout was cleaned and re-colored with new grout colorant. X-PROTECT was applied to the floors and shower walls to provide the gloss appearance desired by the Customer.

On-going maintenance and cleaning with non-harsh chemical cleaners will keep the shower floors and walls looking like new. The xGen coating application provides chemical resistance and a long-term solution that will last 3-5 years and will provide slip resistance on the shower floors.

BEFORE APPLICATION



AFTER APPLICATION



118 Rochester Drive

Louisville, Kentucky 40214

(502) 992-0670

www.xGenCoatings.com